

# Mixer Grinder

Category	Grinder Repair	Jar Repair
Armature issue	On Visit	On Visit
Bush issue	On Visit	On Visit
Carbon Set Field Coil Motor Issue	On Visit	-
Lead issue	Rs.(149-249)*	-
Shaft	On Visit	On Visit
Blade	On Visit	On Visit
Coupling	On Visit	On Visit
Socket	On Visit	On Visit

# Key Highlights

**1-This Rate card includes spare parts as well as labour charges. Visiting cost will be charged extra @Rs. 200 per service.**

**2-If you are not going to repair the problem after technician inspection due to any reason, there will be minimum visiting charges Rs.200 for inspection.**

3-Actual Repair Costs will be provided after diagnosis.

4-All the rates mentioned in our rate card are exclusive of GST.

**5-Get 30 Days of complete Warranty of Repair** (T&C Apply)\*

6-We sell and service all the brands.